

ALC ENVIRONMENTAL
CONSULTING | MANAGEMENT | TRAINING

**Polychlorinated Biphenyl
Assessment**

PERFORMED AT:

20 South 2nd Avenue &
23 South 3rd Avenue
Mt. Vernon, NY 10550

PERFORMED FOR:

Trinity Financial, Inc.
1350 Broadway #1700
New York, NY 10018

REPORT DATE:
December 16, 2021

PREPARED BY

ALC ENVIRONMENTAL
39 West 29th Street, 8th Floor
New York, NY 10001 | 212.675.5544

Christoph Stump
VP Design and Construction
Trinity Financial, Inc.
1350 Broadway #1700
New York, NY 10018

Subject: Polychlorinated Biphenyl Assessment

Location: 20 South 2nd Avenue & 23 South 3rd Avenue, Mt. Vernon, NY, 10550

Dear Mr. Stump,

In accordance with your authorization, ALC Environmental (ALC) has completed polychlorinated biphenyl (PCB) testing at the above referenced addresses. The objective of this assessment was to determine if PCBs are contained in select building materials of the property. ALC EHS Specialist Colin Eckhardt conducted the assessment on November 3, 2021. PCB testing entailed bulk sampling of caulking materials from windows and similar components.

PCB Information

While no longer commercially produced in the United States, PCBs may be present in products and materials produced before its ban of use in 1979. Products that may contain PCBs include oil-based paint, adhesives, caulking, and plastics. The PCBs used in these products were chemical mixtures made up of a variety of individual chlorinated biphenyl components, known as congeners. Most commercial PCB mixtures are known in the United States by their industrial trade names, the most common trade name being Aroclor.

PCBs do not readily break down and therefore may remain in the environment for long periods of time cycling between air, water, and soil. PCBs have been demonstrated to cause cancer, as well as a variety of other adverse health effects on the immune system, reproductive system, nervous system, and endocrine system.

Methods

PCB measurements were collected using bulk sampling. Sufficient pieces of caulking are extracted from a large bulk to represent the intended component. Samples were taken from each different kind of window or similar component. The samples are submitted to EMSL Analytical's Radon Laboratory, located at 200 Route 130 North Cinnaminson, NJ 08077, for analysis.

Results:

20 South 2nd Avenue, Mt. Vernon, NY, 10550
November 3, 2021
PCB Analysis

Sample ID	Sample Location	Sampled Component	Results
1	Room 203	Slide window	ND
2	2 nd floor hallway	Slide window	ND
3	Staircase	Crank window interior	ND
4	Staircase	Crank window exterior	ND
5	2 nd floor meeting room	Crank window	ND
6	Lobby facade	Front door	ND
12	Roof	Caulking material	ND
13	3 rd floor/roof	Window	ND

ND – Not detected

23 South 3rd Avenue, Mt. Vernon, NY, 10550
November 3, 2021

Sample ID	Sample Location	Sampled Component	Results
7	1 st floor gymnasium	Slide window	ND
8	2 nd floor gymnasium	Slide window	ND
9	Ground floor locker room	Slide window	ND
10	Ground floor pool room	Slide window	ND
11	Roof	Caulking material	ND
14	Roof	Window	ND

ND – Not detected

Laboratory Results:

The laboratory results are attached as Appendix A.

Discussion:

- The results of the PCB testing from the materials at the tested addresses are negative.
- **Based on the sample results PCBs are not contained in the selected building materials and may be removed and disposed of under normal construction techniques.**

If you have any questions and/or comments, please contact us directly at 212-675-5544. We appreciate the opportunity to be of service.

Sincerely,
ALC Environmental



Colin Eckhardt
EHS Specialist



Jack Glass, MS, CIH
Vice President, EHS



Carlos Tello
Senior Project Manager, EHS Division

Limitations and Exclusions

All the professional opinions presented in this report are based solely on the scope of work conducted and sources referred to in our report. The data presented by ALC in this report was collected and analyzed using generally accepted industry methods and practices at the time the report was generated. This report represents the conditions, locations, and materials that were observed at the time the fieldwork was conducted. The scope of work for this project did not include an assessment of other environmental conditions which might exist on the premises. No inferences regarding other conditions, locations, or materials, at a later or earlier time may be made based on the contents of the report. No other warranty, express or limited is made. ALC's liability and that of its contractors and subcontractors, arising from any services rendered hereunder, shall not exceed the total fee paid by the client to ALC for this project. This report was prepared for the sole use of our client. The use of this report by anyone other than our client or ALC is strictly prohibited without the expressed written consent of ALC. Portions of this report may not be used independent of the entire report.

Appendix A

EMSL Laboratory Results



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone: (856) 303-2500 Fax: (856) 858-4571 Email: EnvChemistry2@emsl.com

Attn:

**Colin Eckhardt
ALC Environmental
39 West 29th St
New York, NY 10001**

12/3/2021

Phone: (212) 675-5544
Fax: (212) 675-4698

The following analytical report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on 11/8/2021. The results are tabulated on the attached data pages for the following client designated project:

20 South 2nd Avenue-Mt. Vernon

The reference number for these samples is EMSL Order #012112750. Please use this reference when calling about these samples. If you have any questions, please do not hesitate to contact me at (856) 303-2500.

Approved By:

Phillip Worby, Environmental Chemistry
Laboratory Director



The test results contained within this report meet the requirements of NELAP and/or the specific certification program that is applicable, unless otherwise noted.
NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, CA ELAP 1877

Samples -0003 and -0004 could not be reported due to a lab error during the extraction process.

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the NELAP, unless specifically indicated. All results for soil samples are reported on a dry weight basis, unless otherwise noted. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012112750

CustomerID: AMLC50

CustomerPO:

ProjectID:

Attn: **Colin Eckhardt**
ALC Environmental
39 West 29th St
New York, NY 10001

Phone: (212) 675-5544
 Fax: (212) 675-4698
 Received: 11/8/2021 09:00 AM

Project: 20 South 2nd Avenue-Mt. Vernon

Analytical Results

Client Sample Description 1 **Collected:** 11/3/2021 10:00:00 AM **Lab ID:** 012112750-0001

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1016	ND D	0.89 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1221	ND D	0.89 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1232	ND D	0.89 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1242	ND D	0.89 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1248	ND D	0.89 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1254	ND D	0.89 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1260	ND D	0.89 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1262	ND D	0.89 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1268	ND D	0.89 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

Client Sample Description 2 **Collected:** 11/3/2021 10:00:00 AM **Lab ID:** 012112750-0002

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1016	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1221	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1232	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1242	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1248	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1254	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1260	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1262	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012112750

CustomerID: AMLC50

CustomerPO:

ProjectID:

Attn: **Colin Eckhardt**
ALC Environmental
39 West 29th St
New York, NY 10001

Phone: (212) 675-5544
Fax: (212) 675-4698
Received: 11/8/2021 09:00 AM

Project: 20 South 2nd Avenue-Mt. Vernon

Analytical Results

Client Sample Description 2 **Collected:** 11/3/2021 10:00:00 AM **Lab ID:** 012112750-0002

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1268	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00

Client Sample Description 5 **Collected:** 11/3/2021 10:00:00 AM **Lab ID:** 012112750-0005

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1016	ND D	0.68 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1221	ND D	0.68 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1232	ND D	0.68 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1242	ND D	0.68 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1248	ND D	0.68 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1254	ND D	0.68 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1260	ND D	0.68 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1262	ND D	0.68 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1268	ND D	0.68 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00

Client Sample Description 6 **Collected:** 11/3/2021 10:00:00 AM **Lab ID:** 012112750-0006

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1016	ND D	0.90 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1221	ND D	0.90 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1232	ND D	0.90 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00
3546/8082A	Aroclor-1242	ND D	0.90 mg/Kg	11/9/2021 ER	11/10/2021 TL 00:00

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012112750

CustomerID: AMLC50

CustomerPO:

ProjectID:

Attn: **Colin Eckhardt**
ALC Environmental
39 West 29th St
New York, NY 10001

Phone: (212) 675-5544
 Fax: (212) 675-4698
 Received: 11/8/2021 09:00 AM

Project: 20 South 2nd Avenue-Mt. Vernon

Analytical Results

Client Sample Description 6 **Collected:** 11/3/2021 10:00:00 AM **Lab ID:** 012112750-0006

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1248	ND D	0.90 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1254	ND D	0.90 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1260	ND D	0.90 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1262	ND D	0.90 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1268	ND D	0.90 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

Client Sample Description 7 **Collected:** 11/3/2021 11:00:00 AM **Lab ID:** 012112750-0007

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1016	ND D	0.93 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1221	ND D	0.93 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1232	ND D	0.93 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1242	ND D	0.93 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1248	ND D	0.93 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1254	ND D	0.93 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1260	ND D	0.93 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1262	ND D	0.93 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1268	ND D	0.93 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

Client Sample Description 8 **Collected:** 11/3/2021 11:00:00 AM **Lab ID:** 012112750-0008

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012112750

CustomerID: AMLC50

CustomerPO:

ProjectID:

Attn: **Colin Eckhardt**
ALC Environmental
39 West 29th St
New York, NY 10001

Phone: (212) 675-5544
 Fax: (212) 675-4698
 Received: 11/8/2021 09:00 AM

Project: 20 South 2nd Avenue-Mt. Vernon

Analytical Results**Client Sample Description** 8
Collected: 11/3/2021
 11:00:00 AM
Lab ID: 012112750-0008

Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
GC-SVOA							
3546/8082A	Aroclor-1016	ND D	0.93 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1221	ND D	0.93 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1232	ND D	0.93 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1242	ND D	0.93 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1248	ND D	0.93 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1254	ND D	0.93 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1260	ND D	0.93 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1262	ND D	0.93 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1268	ND D	0.93 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL

Client Sample Description 9
Collected: 11/3/2021
 11:00:00 AM
Lab ID: 012112750-0009

Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
GC-SVOA							
3546/8082A	Aroclor-1016	ND D	0.97 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1221	ND D	0.97 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1232	ND D	0.97 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1242	ND D	0.97 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1248	ND D	0.97 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1254	ND D	0.97 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1260	ND D	0.97 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1262	ND D	0.97 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012112750

CustomerID: AMLC50

CustomerPO:

ProjectID:

Attn: **Colin Eckhardt**
ALC Environmental
39 West 29th St
New York, NY 10001

Phone: (212) 675-5544
 Fax: (212) 675-4698
 Received: 11/8/2021 09:00 AM

Project: 20 South 2nd Avenue-Mt. Vernon

Analytical Results

Client Sample Description 9 **Collected:** 11/3/2021 11:00:00 AM **Lab ID:** 012112750-0009

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1268	ND D	0.97 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

Client Sample Description 10 **Collected:** 11/3/2021 11:00:00 AM **Lab ID:** 012112750-0010

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1016	ND D	0.88 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1221	ND D	0.88 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1232	ND D	0.88 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1242	ND D	0.88 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1248	ND D	0.88 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1254	ND D	0.88 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1260	ND D	0.88 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1262	ND D	0.88 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1268	ND D	0.88 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

Client Sample Description 11 **Collected:** 11/3/2021 11:00:00 AM **Lab ID:** 012112750-0011

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1016	ND D	0.87 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1221	ND D	0.87 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1232	ND D	0.87 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1242	ND D	0.87 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012112750

CustomerID: AMLC50

CustomerPO:

ProjectID:

Attn: **Colin Eckhardt**
ALC Environmental
39 West 29th St
New York, NY 10001

Phone: (212) 675-5544
 Fax: (212) 675-4698
 Received: 11/8/2021 09:00 AM

Project: 20 South 2nd Avenue-Mt. Vernon

Analytical Results

Client Sample Description 11 **Collected:** 11/3/2021 11:00:00 AM **Lab ID:** 012112750-0011

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1248	ND D	0.87 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1254	ND D	0.87 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1260	ND D	0.87 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1262	ND D	0.87 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1268	ND D	0.87 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

Client Sample Description 12 **Collected:** 11/3/2021 11:00:00 AM **Lab ID:** 012112750-0012

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1016	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1221	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1232	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1242	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1248	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1254	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1260	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1262	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL
3546/8082A	Aroclor-1268	ND D	0.92 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

Client Sample Description 13 **Collected:** 11/3/2021 11:00:00 AM **Lab ID:** 012112750-0013

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012112750

CustomerID: AMLC50

CustomerPO:

ProjectID:

Attn: **Colin Eckhardt**
ALC Environmental
39 West 29th St
New York, NY 10001

Phone: (212) 675-5544
 Fax: (212) 675-4698
 Received: 11/8/2021 09:00 AM

Project: 20 South 2nd Avenue-Mt. Vernon

Analytical Results**Client Sample Description** 13
Collected: 11/3/2021
 11:00:00 AM
Lab ID: 012112750-0013

Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
GC-SVOA							
3546/8082A	Aroclor-1016	ND D	0.91 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1221	ND D	0.91 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1232	ND D	0.91 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1242	ND D	0.91 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1248	ND D	0.91 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1254	ND D	0.91 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1260	ND D	0.91 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1262	ND D	0.91 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1268	ND D	0.91 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL

Client Sample Description 14
Collected: 11/3/2021
 11:00:00 AM
Lab ID: 012112750-0014

Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
GC-SVOA							
3546/8082A	Aroclor-1016	ND D	0.98 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1221	ND D	0.98 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1232	ND D	0.98 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1242	ND D	0.98 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1248	ND D	0.98 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1254	ND D	0.98 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1260	ND D	0.98 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL
3546/8082A	Aroclor-1262	ND D	0.98 mg/Kg	11/9/2021	ER	11/10/2021 00:00	TL

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012112750

CustomerID: AMLC50

CustomerPO:

ProjectID:

Attn: **Colin Eckhardt**
ALC Environmental
39 West 29th St
New York, NY 10001

Phone: (212) 675-5544
Fax: (212) 675-4698
Received: 11/8/2021 09:00 AM

Project: 20 South 2nd Avenue-Mt. Vernon

Analytical Results**Client Sample Description** 14**Collected:** 11/3/2021
11:00:00 AM**Lab ID:** 012112750-0014

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
GC-SVOA					
3546/8082A	Aroclor-1268	ND D	0.98 mg/Kg	11/9/2021 ER	11/10/2021 00:00 TL

Definitions:

MDL - method detection limit

J - Result was below the reporting limit, but at or above the MDL

ND - indicates that the analyte was not detected at the reporting limit

RL - Reporting Limit (Analytical)

D - Dilution Sample required a dilution which was used to calculate final results